ClearOne

PRODUCTS SUPPORTED:

RELEASE NOTES

COLLABORATE® Versa Lite CT
COLLABORATE® Versa Room CT

CONSOLE® AI Lite
SOFTWARE AND FIRMWARE RELEASE NOTES

RELEASE 02Jun2020

Initial Product Release

CONSOLE AI Lite v1.0.15.0

COLLABORATE Versa USB v1.0.1.34

BMA CTH v1.1.0.8

Bluetooth Expander v1.0.1.18

Known Issues

1. The LED on the PoE Input port on the Versa USB does not light up when you apply power. Instead, to check for power, look at the Power LED on the front panel.
2. If, while connected, you unplug the Versa USB device, the connection icon in CONSOLE AI Lite appears as though you can connect again. If you click the icon, you receive a connection error.
3. If you unplug the BMA CTH or the Bluetooth Expander from the Versa USB, CONSOLE AI Lite continues to display the firmware version and the serial number, even though they are not connected.
4. The BMA CTH Mic mute mirrors the status of the microphone mute on the computer. This means if the microphone is muted in the conferencing software, then the BMA CTH Mic is also muted. However, mute sync does not work in the opposite direction-- muting the BMA CTH Mic does not mute the conferencing software.
5. Polarity in the Speaker channels is not reset to off when the "Restore Factory Defaults" button is pressed.
6. The Disable Bluetooth property may not be set correctly on the device when you load a project with the property disabled. The property may be changed while connected with Console AI Lite or by pressing the button on the Bluetooth device.