

TECHNICAL NOTE

→ RAV RAV-WARE 101

Running RAV 600/900 Web Server Interface with Java 1.5.0

Description

The web browser locks up when accessing web interface functions in the RAV 600/900 when using Java 1.5.0.

An issue has been identified with the latest release of Sun's Java software version 1.5.0 (also called version 5). The browser connects to the RAV 600/900 web server interface, but fails moments later. The result is that the RAV 600/900 interface indicates a loss of connection and the browser locks up and will not respond to any button clicks, which requires the user to use the Windows task manager to end the process.

This has been determined to be a JavaScript handling error in Sun's latest release. Sun is aware of the issue, but it is unknown whether they will fix the error. Previous versions of Java do not exhibit this issue.

Resolution

The RAV 600/900 web interface is compatible with Java version 1.4.2 and earlier, which is available from Sun for download at <http://java.sun.com/j2se/1.4.2/download.html>.

The version available to download and install on your PC is J2SE v 1.4.2_07 JRE, which includes the JVM technology.

Uninstall Java 1.5 and then install version 1.4.2 to ensure proper functioning of the RAV 600/900 web interface.

→ CLEARONE LOCATIONS

Headquarters:
Salt Lake City, UT USA
1825 Research Way
Salt Lake City, UT 84119
Tel: 801-975-7200;
800-945-7730
Fax: 801-977-0087
sales@clearone.com

Champlin, MN USA
Tel: 801-942-3776
sales@clearone.com

Latin America Offices
Tel: 801-974-3621
global@clearone.com

London, UK
Tel: 801-974-3792
global@clearone.com

Hong Kong
Tel: 801-303-3441
global@clearone.com

Singapore
Tel: 801-303-3495
global@clearone.com